



406 - 22 Avenue  
Nisku, AB, T9E 7W8  
Ph: 780-979-0390 • Fax: 780-979-9964  
www.seicor.ca

## EQUIPMENT CERTIFICATION

May 10, 2019

**E-715**

Issued to:  
Gilliss Casing Services Inc.  
Box 1055  
Estevan, SK S4A 2H7

|                                    |  |
|------------------------------------|--|
| <b>Equipment:</b>                  | <b>BJ Casing Elevator, TA 150, 7" x 90°, 150 Ton</b> |
| <b>Model:</b>                      | <b>TA 150</b>  |
| <b>Serial Number:</b>              | <b>270690</b>  |
| <b>SEICOR Inspection Report #:</b> | <b>SE-1088</b>                                       |
| <b>SEICOR W.O. #:</b>              | <b>1288</b>  |
| <b>Engineering File Number:</b>    | <b>19050831</b>                                      |
| <b>Load Test #:</b>                | <b>57476B</b>  |

A Level IV inspection was performed on the equipment listed above. As per CAODC RP 4.0, the equipment was inspected and certified for service.

The equipment was disassembled and was stripped to bare metal prior to inspection. SEICOR International Inc. performed visual and magnetic particle inspections on all accessible areas. Critical dimensions of the equipment were measured and conform to the manufacturer's rating. The elevator was load tested to 225 tons (450,000 lbs).

Based on the equipment critical dimensions, load testing, and inspection, it is our opinion that this equipment can enter service and operate according to the manufacturer's directions and ratings.

In accordance with CAODC Recommended Practice, a Level IV inspection is required after 6 calendar years, or after the unit has been damaged structurally because of handling, transportation, or operation. Periodic inspection and maintenance are required at recommended intervals.

