



ALCO INC. HEAD OFFICE
6925 - 104 Street, Edmonton, Alberta T6H 2L5
Office: (780) 435-3502
Website: www.alcoinc.ca

E-717

August 21, 2019

Gilliss Casing Services
P.O. Box 1055
Estevan, SK.
S4A 2H7

Certificate of Conformance

CUSTOMER:	Gilliss Casing Services
CUSTOMER EQUIPMENT #:	717 - 41101
CUSTOMER RIG #:	N/A
EQUIPMENT DESCRIPTION:	RT Center Latch Casing Elevator
MODEL AND RATING: 100 Tons	7" - 90° - TA-100, 100 Tons (88964-daN)
INSPECTION COMPANY / REPORT #:	Alco / H - N/A
ALCO ENGINEERING FILE #:	64208-1-E
ALCO WORK ORDER #:	64208-1

This document specifies that all parts and/or assemblies for the equipment referenced above are sold under the manufacturer's warranty.

The above referenced items are to be used according to the manufacturer's directions and ratings. Alco assumes no responsibility for defective parts or assemblies or any costs associated with their repair due to normal use or misuse.

Manufacturer's documentation indicate a load test to 1.5 times this component's rating has been done. Material ductility requirements conform to those specified by the American Petroleum Institute's (API) section 8c.

A CAODC Recommended Practice Level IV inspection is typically required after: 500 operating days.

Brian Kulak, P.Eng
Engineering Manager
Alco Inc.

