

803



ALCO Inc.

6925 - 104 Street, Edmonton, Alberta, Canada T6H 2L5
Phone: (780) 435-3502 • Fax: (780) 436-1858

- ALCO MACHINE WORKS
- ALCO FLOW CONTROL
- ALCO PRODUCTION MACHINE SHOP

December 11, 2003

Gator Oilfield Supply
5312 – 89th Street
Edmonton, Alberta
T6E 5P9

Equipment Certification

Equipment: BJ Side Door Casing Elevator
Model: 8-5/8" x 90°, SLX 150-Ton
Serial No.: 12698
Hydra Inspection Report No.: H-12698
Engineering File No.: 58330-E


The above-mentioned elevator required a Level IV inspection (as per Canadian Association of Oilwell Drilling Contractors, R.P. 2.0), applicable repairs, and certification for service. The elevator has been retrofitted with a door safety latch pin.

Hydra Group Ltd. conducted a magnetic particle (MT) inspection on November 27, 2003, after the elevator was completely disassembled and sandblasted.

Repair procedures were developed based on the MT inspection report as well as a thorough visual examination performed by qualified personnel with Alco Machine Works.

Based on the final inspection on December 11, 2003, after load testing, it is our opinion that the elevator is a safe operating unit and may be returned to service within the manufacturer's original rating and specification.

This certification is valid for a period of 500 operating days, as per the recommendations provided by the Canadian Association of Oilwell Drilling Contractors, or until the elevator has been damaged either as a result of operation, transportation or handling.



<p>PERMIT TO PRACTICE ALCO MACHINE WORKS</p> <p>Signature _____</p> <p>Date <u>December 11, 2003</u></p> <p>PERMIT NUMBER: P7208 The Association of Professional Engineers, Geologists and Geophysicists of Alberta</p>
