



**ALCO INC. HEAD OFFICE**  
 6925 - 104 Street, Edmonton, Alberta T6H 2L5  
 Office: (780) 435-3502  
 Website: www.alcoinc.ca

E-916

November 5, 2021

Gilliss Casing Services  
 P.O. Box 1055  
 Estevan, SK.  
 S4A 2H7

**Certificate of Conformance**




<b>CUSTOMER:</b>	Gilliss Casing Services
<b>CUSTOMER EQUIPMENT # :</b>	2107104
<b>CUSTOMER RIG # :</b>	N/A
<b>EQUIPMENT DESCRIPTION:</b>	RT Single Joint Casing Elevator
<b>MODEL AND RATING:            5 Tons</b>	9 5/8" - 5 Ton (4448-daN)
<b>INSPECTION COMPANY / REPORT #:</b>	Alco / H-N/A
<b>ALCO ENGINEERING FILE # :</b>	71668-2-E
<b>ALCO WORK ORDER # :</b>	71668-2

This document specifies that all parts and/or assemblies for the equipment referenced above are sold under the manufacturer's warranty.

The above referenced items are to be used according to the manufacturer's directions and ratings. Alco assumes no responsibility for defective parts or assemblies or any costs associated with their repair due to normal use or misuse.

Manufacture's documentation indicate a load test to 1.5 times this component's rating has been done. Material ductility requirements conform to those specified by the American Petroleum Institute's (API) section 8c.

A CAODC Recommended Practice Level IV inspection is typically required after: 500 operating days.

 2021-11-05 <b>Brian Kulak, P.Eng</b> Engineering Manager Alco Inc.		<p><b>PERMIT TO PRACTICE</b>          ALCO INC., GENERAL PARTNER OF THE          ALCO LIMITED PARTNERSHIP</p> <p>RM SIGNATURE:           RM APEGA ID #: 30312          DATE: Nov 5 2021</p> <p><b>PERMIT NUMBER: P010702</b>          The Association of Professional Engineers and Geoscientists of Alberta (APEGA)</p>
--	---	---